



Volvo XC 60: 2CHE249				
Vinnumber:	YV1UZH1V2P1218634	Versionname:		
First Registrationdate:	27/07/2022	Fiscalpower:		
Expertise Mileage:	110433	Power Kw:		
Bodytype:		Body colour		Black
Gearbox:	Automatic	Type of rims (mounted)		Aluminium
Transmission:		Parking lot		3104
Fueltype:	Petrol			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Sun Roof electric		
Cruise Control		Panoramic roof		
Steering wheel multifunctional		Luggage cover		
Seats F heated		Front parking sensors		
Radio multimedia		Rear parking sensors		
Type of headlighting	Headlighting LED	Type of Tow bar		No Tow bar
Type of GPS	GPS big screen color			
Type of Lining	Lining artificial leather			
Type of climate control	Autom climate control			
Type of GPS storage	HD			
Limited Technical Inspection				
Tyres				
	225/50/17/98 Y			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/50 R 17 98 Y
Tyre size FR				225/50 R 17 98 Y
Tyre size RL				225/50 R 17 98 Y
Tyre size RR				235/55 R 19 101 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261
Assistance equipment				
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	1			
Total cost ex VAT				2209,47
Interior, Worn, Acceptable				0,00



Floor covering FL, Hole, Replace	251,81
----------------------------------	--------




Engine insulation, Damaged, Replace	173,94
-------------------------------------	--------



Bonnet, Scratch(es), Repair and paint (complete)	487,44
--	--------



Wing RL, Scratch(es), Polish	0,00
------------------------------	------



Alloy rim RL polished, Scratch(es), Acceptable	0,00
--	------



Wing FL, Scratch(es), Repair and paint (complete)	369,97
---	--------



Alloy rim FL polished, Scratch(es), Acceptable	0,00
--	------



Charging cable (normal), Missing, Replace	0,00
---	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------




Alloy rim RR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing RR, Scratch(es), Repair and paint (complete)	517,89
---	--------



Step R, Scratch(es), Acceptable	0,00
---------------------------------	------



Bodywork, Chemical polution, Cleaning	0,00
---------------------------------------	------

