

Renault

MEGANE-SW IV EST BDCI 115 EDC FR TECHNO

VIN: VF1RFB00472689409



Description

Registration number	Registration date	Odometer
GX-550-CT	27/05/2024	74853 km
Color	Year	Upholstery
Black	-	-
Number of doors	Number of seats	Generation
-	-	-
Body Type	Vehicle Type	Engine type
Estate	Passenger car	Combustion
Fuel Type	Max power	
Diesel	115 HP	

Vehicle Equipments

Rear-view camera	Climate control	Alloy wheel rims
Rear sensors	Cruise control	SATNAV
Front sensors	Sliding roof	

Statement details

Inspection loc	Statement date	Inspection approval date
EUROPCAR MARLY	22/07/2026	23/07/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	799 / Front Right ¹	Broken	Replace

	 		
002	Rim / Front Left Rim/Tyre diameter : 17 " / Surface : Machine polished	Scratched	Repair
	 		
003	Rim / Front Right Rim/Tyre diameter : 17 " / Surface : Machine polished	Scratched	Repair
	 		
004	Rim / Back Right Rim/Tyre diameter : 17 " / Surface : Machine polished	Scratched	Repair
	 		
005	Tyre / Back Left Rim/Tyre diameter : 17 "	Tear	Replace
	 		
006	Rim / Back Left Rim/Tyre diameter : 17 " / Surface : Machine polished	Scratched	Smart repair
	 		
007	Door / Front Left	Dent	Repair

			
008	Wing / Back Left	Dent	Smart repair
			
009	Roof / - Sunroof : Yes	Dent	Acceptable
			
010	Bumper / Back	Scratched	Painting
			
011	Door entry seal / Back	Broken	Replace
			
012	Exterior door mirror shell / Right	Scratched	Painting
			
013	Sill / Right	Dent	Repair
			

014	Bumper / Front	Dent	Repair
			
015	Bonnet / -	Dent	Repair
			
016	Windscreen / -	Chip	Smart repair
			

¹ Poignée de maintien AVD

Loose Items

- ☐ Slow charging cable (Type 2, Mode 2)

☒ Warranty booklet

☒ Remote key

☐ Cargo net

☐ Rear parcel shelf
- ☐ Quick charging cable (Type 2, Mode 3)

☐ Memory card

☐ Compressor tyre repair kit

☐ Separation net

☐ Refill tyre repair kit
- ☒ Load cover

☐ Locking wheel nut

☒ Jack

☒ User manual

☒ Spare wheel tyre

Main set of tyres

Front Left	TIGAR	205 / 50 / 17 / Summer	5 mm
Front Right	TIGAR	205 / 50 / 17 / Summer	4.8 mm
Back Left	CONTINENTAL	205 / 50 / 17 / Summer	5 mm
Back Right	CONTINENTAL	205 / 50 / 17 / Summer	5 mm
Back		/// Summer	7 mm

Pictures



Front left



Rear



Boot opened



Rear right



Dashboard from rear seat



Front passenger compartment



Odometer



Navigation



Vin



Other



799 / Front Right / Broken



799 / Front Right / Broken



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Back Right / Scratched



Rim / Back Right / Scratched



Tyre / Back Left / Tear



Tyre / Back Left / Tear



Rim / Back Left / Scratched



Rim / Back Left / Scratched



Door / Front Left / Dent



Door / Front Left / Dent



Wing / Back Left / Dent



Wing / Back Left / Dent



Roof / - / Dent



Roof / - / Dent



Bumper / Back / Scratched



Bumper / Back / Scratched



Door entry seal / Back / Broken



Door entry seal / Back / Broken



Exterior door mirror shell / Right / Scratched



Exterior door mirror shell / Right / Scratched



Sill / Right / Dent




Sill / Right / Dent



Bumper / Front / Dent



Bumper / Front / Dent



Bonnet / - / Dent



Bonnet / - / Dent



Windscreen / - / Chip



Windscreen / - / Chip

